



PROJECT 002

OVIE SCHOOL REALITY INITIATIVE

Government Schools - From Facilities to Solutions

ABOUT THE COMPANY

THE OVIE CIRCLE FOUNDATION is a Section 8 Company incorporated under the Companies Act, 2013. The Company works in education, social development, public awareness, rural development and purposeful social action.

PURPOSE OF VISIT

Under PROJECT 002 - OVIE SCHOOL REALITY INITIATIVE, the Company undertakes a factual assessment of basic facilities available to students in Government Schools.

- Observe the basic facilities available to students.
- Identify genuine deficiencies or requirements, if any.
- Document the actual ground situation and supporting evidence.
- Identify practical areas where improvement may be required.
- Support appropriate resolution of verified issues through engagement with concerned authorities.

This initiative concerns student facilities and their improvement; it is not an assessment of the personal performance of any teacher or school employee.

VISIT & SCHOOL IDENTIFICATION

Date of Visit	19-08-2026
School Name	PRATHMIK PATHSHALA
UDISE Code	09150100901
Village	LADHAM
Block	Akola
District	Agra
Total Teachers	4
Total Students	53



SCHOOL BASIC FACILITY ASSESSMENT

Choose the most accurate status observed during the visit.

1. Classrooms	Available - Improvement Required
2. Electricity / Fans / Lights	Available - Improvement Required
3. Drinking Water	Available & Functional
4A. Boys' Toilet	Available & Functional
4B. Girls' Toilet	Available & Functional
5. Handwash Facility	Not Available
6. Boundary / Safety	Satisfactory
7. Library / Reading Facility	Not Available
8. Playground / Sports	Adequate
9. Digital Facilities	Select status
10. PM POSHAN / Kitchen	Not Available
11. General Cleanliness	Satisfactory

OVERALL FACILITY STATUS

Minor Improvements Required	Assessment Date	19-08-2026
-----------------------------	-----------------	------------

Assessed By	Founder and Director - Avinash Katara and Director - Ayush Sharma	
-------------	---	--



OBSERVED DEFICIENCIES & FIELD EVIDENCE

Record up to three priority issues and supporting evidence.

ISSUE 01

Facility / Area	Boundary / Safety		
Deficiency Observed	Select deficiency		
Current Condition	Unsafe / Urgent Attention		
Evidence Type	Photograph	Evidence No.	1
Students Affected	Not yet		

ISSUE 02

Facility / Area	Drinking Water		
Deficiency Observed	Minor Deficiency		
Current Condition	Satisfactory		
Evidence Type	Photograph	Evidence No.	2
Students Affected	No		

ISSUE 03

Facility / Area	Select facility / area		
Deficiency Observed	Select deficiency		
Current Condition	Select condition		
Evidence Type	Select	Evidence No.	Select Evidence No.
Students Affected			

SCHOOL ADMINISTRATION'S COMMENTS

Nil			
Previously Reported?	Select	Concerned Authority	Basic Shiksha Adhikari (BSA)



SCHOOL ADMINISTRATION & TEACHERS' SUGGESTIONS / REQUESTS

Record views communicated by school representatives.

HEAD TEACHER / PRINCIPAL

Name	PRIYA SINGHAL	Designation	Principal
Principal Priya Singhal ji had gone to MD JAIN INTER COLLEGE AGRA training			
Authority support required?	Select	Previously reported?	Select
Details / Reference	NIL		
Signature / Initials	NIL		

TEACHER - 01

Name	SANJAY KUMAR	Designation	Teacher
He requested that the balcony is broken from many places and is in a state of collapse anytime			
Signature / Initials			

TEACHER - 02

Name	NIL	Designation	Select designation
NIL			
Signature / Initials	NIL		

OTHER SCHOOL STAFF / REPRESENTATIVE

Name	NIL	Designation	Select designation
NIL			
Signature / Initials	NIL		

ASSESSMENT

Assessed by	Founder and Director - Avinash Katara and Director - Ayush Sharma
-------------	---

विद्यालय रसोई घर
निर्माण वर्ष- 2006-07

क्र.सं	दिन	नवीन मेन्यू
	सोमवार	दाल, सब्जी, चने, मीठा, फल, सब्जी
	मंगलवार	चने, दाल, सब्जी, मीठा, फल, सब्जी
	बुधवार	दाल, सब्जी, चने, मीठा, फल, सब्जी
	गुरुवार	दाल, सब्जी, चने, मीठा, फल, सब्जी
	शुक्रवार	दाल, सब्जी, चने, मीठा, फल, सब्जी
	शनिवार	दाल, सब्जी, चने, मीठा, फल, सब्जी

GPS Map Camera

Mankenda, Uttar Pradesh, India



3wpc+rcx, Mankenda, Uttar Pradesh 283102, India


Lat 27.087166° Long 77.921015°

Wednesday, 19/08/2026 11:26 AM GMT +05:30

Google



GPS Map Camera



Mankenda, Uttar Pradesh, India




3wpc+rcx, Mankenda, Uttar Pradesh 283102, India

Lat 27.087245° Long 77.92111°

Wednesday, 19/08/2026 11:27 AM GMT +05:30



GPS Map Camera



Mankenda, Uttar Pradesh, India




3wpc+rcx, Mankenda, Uttar Pradesh 283102, India

Lat 27.087233° Long 77.921111°

Wednesday, 19/08/2026 11:27 AM GMT +05:30



 GPS Map Camera



Mankenda, Uttar Pradesh, India



3wpc+rcx, Mankenda, Uttar Pradesh 283102, India

Lat 27.08723° Long 77.921103°

Wednesday, 19/08/2026 11:27 AM GMT +05:30